
WV Department of Health and Human Resources Bureau of Public Health Office of Environmental Health Services

ENVIRONMENTAL ENGINEERING DIVISION



WELL COMPLETION REPORT

Date(s) 4 _ 1 0 _ 0	6Cou	nty <u>Ha</u> ı	npsh	ire	Permit #: _DW1406261
Town: Shanks	Area	Name/L	ocation.	Na	thaniel Park Estates LOt 19
Well Owner: Glen F. Carder				-	Address: 154 Hamlin Drive
Telephone Number: (540)373-8039				_	Fredericksburg VA 22405
Well Driller: Mill	er Brothers D	rill:	ing-	LLC	Address: PO Box 952
	(304)822-4092				Romney WV 26757
WELL LOG					
DEPTH IN FEET	FORMATIONS: KIND, THICKNESS, AND IF WATER BEARING				REMARKS:
0-48	Yellow & bro	wn sl	nale		Type of Well: <u>Drilled</u> Drilling Method: <u>Air rotary</u>
	Blue shale				Well Diameter: 61 Casing O.D.: 71
48-66			*		Well Depth: 420 Date Completed: 4-10-06
66-84	Brown shale				CASING: Length 60 Feet Helght above ground 1 Feet
84-420	Blue shale				☐ Steel 🖾 Plastic ☐ Cast Iron
					Other
					Туре
					SCREEN
		,			CX None Installed
-				-	Type Diameter
			W.S.		Slot/Gauge Length
0					Set Between Ft. and Ft.
					Te did
					A STATE OF THE STA
PUMPING OR BAILI	NG TEST				WELL HEAD
DETAILS		#1	#2	#3	Pitless Adapter: Type, Make, Etc.
Static Water Level (Ft. Below Grade)		100			Well Cap: Type, Make, Etc.
Pumping Rate (GPN	5			Well Seal: Type, Make, Etc.	
Pumping Level (Ft. Below Grade)					Well Platform:
	418			Length Width Thickness	
Duration of Test (In Hours)		2			Grouting: ※☑ Yes □ No
Recovery Time to Static Level (In Hours)					All Public Water Supplies must be grouted.
	nis well was drilled and cor ny knowledge and belief.	nstructed	under	my sup	pervision, in compliance with all requirements of the referenced permit, and that this record
					Bobby Allred 602
					Name Certification No. Miller Brothers Drilling LLC 4-10-06
					Redistered Business Name
					Signed Date

\$\$ 177 7/96	STATE OF WEST VIRGINIA	Permit No.: ST-14-66-342						
INSPECTION TO BE PRINTED OR TYPED	Chica HEALTH DEPARTMENT	Permit No.:						
	-SITE SEWAGE DISPOSAL SYSTEM	Tax Map: 32 Parcel #: 16						
County: formalahin ON	INSPECTION FORM	County Road:						
Name of Owner: CICEN	ARDER Installer: El	DRIDGE C. MORE LINED SA						
	DK. FREDERICKSBURY, UA	22.405						
Property Location: ##777	2001 1 2212 201011212	12 1 100 100						
Type of Facility : Property	OFER TO ETAP, TURN LEFT (C EE Facility is: New Y-LExisting ()	In Sing E and a So To So						
Type of Facility : CESIDELI	Pacinty is: New / Existing ()	Lot Size: 3.22 Sq. Ft. Acres						
Design Loading in gpd/No. Bedrooms: Source of Water Supply: AFTE								
SEWAGE TANK COMPONENT								
Capacity in Gallons: 1077 Material: Conclude Manufacturer:								
Distances (in feet) of Tank to: Dwelling: 25 Private PS/Public () Water Source: 75 Property Line: 126								
7	ON-SITE DISPOSAL SYSTEM							
Class I Systems: Standard Soil A	bsorption Trenches () or Bed () Gravelless	Pipe (), Diameter: Inches						
Chamber Soil Absorption Trenches 📈 or Bed ()								
Class II Systems: Pumped/Dosed Soil Absorption Trenches () or Bed () Evapotranspiration Trenches () or Bed ()								
	oil Absorption Trenches () or Bed () Other:_							
No. of Lines: 3 Length (in	feet) of Each: <u>\$\mathcal{GU}, \mathcal{S}\mathcal{S}, \mathcal{Z}\mathcal{F}, \text{P}}, \text{The control of Field: \text{L}\mathcal{F}</u>							
Width of Trenches: 3	nches/feet Depth to Bottom of Field: 24	inches						
	If Chamber System, Name:							
Approved and Adequate Materials	Used? Yes No () Size Equates to: 1200	Severe Food of Standard Count Field						
Approved and Adequate materials	Oseur res y// No () Size Equates to. 7200	Square reet of Standard Graver Fleid						
	Dwelling: 60 Private (<)/Public () Water So	ource: 75 Property Line: 70						
Remarks:								
- Company of the large of the l								
An inspection indicates that	Sketch of Installation with Triangulation or Dis	tance to Specific Landmarks:						
the sewage disposal system								
described above	T I CUI DENNEZ	Collected Right						
DOES MEET M.		Draw Array						
DOES NOT MEET (),		Draw Arrow toward North						
CANNOT BE DETERMINED TO		V35 TO TANK						
MEET () the minimum standards		25 TO TANK POLO						
established by the West Virginia	111	15 100 100						
Bureau of Public Health.	I I	1						
To correct a health hazard,	1	1						
modifications to existing systems may be done to improve part of a	% %c	25						
system. Such modifications may	N	7						
not be able to be designated as a	80 11	21						
does meet system since	1 2c 11	19						
inadequate information is known.	82)						
Although many factors	1 40 -1-	ž						
contribute to the successful								
functioning of a sewage disposal		i						
system, this office recommends								
water conservation and								
maintaining an even usage of	- E							
water throughout the week.	<u> </u>							
A wil								
Visit Date(s): 3-24-0	6)						